



**PEUGEOT BOXER : 1DFU817**

|                                   |                                 |              |               |
|-----------------------------------|---------------------------------|--------------|---------------|
| Vinnumber:                        | <b>VF3YC2MFC12D53901</b>        | Versionname: |               |
| First Registrationdate:           | <b>30/03/2017</b>               | Fiscalpower: |               |
| Expertise Mileage:                | <b>70558</b>                    | Power Kw:    | <b>96</b>     |
| Bodytype:                         | <b>Transporter</b>              | Body color   | <b>White</b>  |
| Gearbox:                          | <b>MAN 6 VIT</b>                | Paint type   | <b>Opaque</b> |
| Transmission:                     | <b>Front</b>                    | Rims summer  | <b>Steel</b>  |
| Fueltype:                         | <b>Diesel</b>                   | Oil level    | <b>OK</b>     |
| Maintenance                       | <b>OK</b>                       | Parking lot  | <b>LCV21</b>  |
| Battery functioning               | <b>Yes</b>                      |              |               |
| Number of doors                   | <b>5</b>                        |              |               |
| Number of seats                   | <b>3</b>                        |              |               |
| Number head rests                 | <b>3</b>                        |              |               |
| Rims summer                       | <b>Steel</b>                    |              |               |
| Category                          | <b>Light Commercial Vehicle</b> |              |               |
| Oil level                         | <b>OK</b>                       |              |               |
| Registration Certificate Car (BE) | <b>Yes</b>                      |              |               |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| GPS storage                    | Rear parking sensors         |
| GPS storage                    | <b>HD</b> Type of Tow bar    |
| Windows electric F             | <b>No Tow bar</b>            |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                              |       |                            |       |                            |
|------------------------------|-------|----------------------------|-------|----------------------------|
| <b>215/70/15/109 S Steel</b> |       |                            |       |                            |
| Summer tyres:                | Fr.L. | <b>Continental: 2,5 mm</b> | Fr.R. | <b>Continental: 2,5 mm</b> |
|                              | Re.L. | <b>Continental: 5 mm</b>   | Re.R. | <b>Continental: 5 mm</b>   |

**Assistance equipment**

|                                                    |            |      |               |
|----------------------------------------------------|------------|------|---------------|
| Spare wheel                                        | <b>Yes</b> | Jack | <b>Yes</b>    |
| Total cost ex VAT                                  |            |      | <b>100,00</b> |
| Rearview mirror housing L, Scratch(es), Acceptable |            |      | <b>0,00</b>   |
| <i>No pictures to display</i>                      |            |      |               |
| Bumper corner R R, Scratch(es), Acceptable         |            |      | <b>0,00</b>   |
| <i>No pictures to display</i>                      |            |      |               |
| Bumper cover R M, Scratch(es), E - Replace         |            |      | <b>100,00</b> |



|                                                    |      |
|----------------------------------------------------|------|
| Bumper corner R L, Scratch(es), Acceptable         | 0,00 |
| No pictures to display                             |      |
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
| No pictures to display                             |      |