



VOLKSWAGEN Polo: 1FVX080

Vinnumber:	WVWZZZ6RZEY111709	Versionname:	POLO Trendline DPF 75PK
First Registrationdate:	13/11/2013	Fiscalpower:	
Expertise Mileage:	136709	Power Kw:	55
Bodytype:		Body color	White
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1114
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Type of headlighting	Type of Tow bar
Type of GPS	No Tow bar
Type of Lining	Lining fabrics

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	175/70/14/84 T Steel			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Total cost ex VAT	140,56
Bumper corner R L, Scratch(es), It - Spot repair	115,56



Seat cover F R, Dirty, Cleaning	25,00
---------------------------------	-------



Bodywork, Glue residues, Remove lettering

0,00

No pictures to display