


RENAULT Kangoo Express: 1FVX844

Vinnumber:	VF1FW14C549452094	Versionname:	KANGOO EXPR.B/F Access Confort 75PK
First Registrationdate:	13/11/2013	Fiscalpower:	
Expertise Mileage:	110408	Power Kw:	55
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2410
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	No climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1202,54
-------------------	----------------

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Rear spoiler, Rust, LI - Repair and paint (complete)	115,56
--	---------------



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	-------------

No pictures to display

Bumper F, Crack, E - Replace		398,40
		
Door panel F L, Broken, E - Replace		91,50
		
Bumper R, Dent(s) and scratch(es), Acceptable		0,00
No pictures to display		
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)		382,76
		
Seat cover F L, Hole, Smart repair		64,32
		
Bodywork, Not original part, Acceptable		0,00
No pictures to display		
Sidewall RL (LCV), Dent(s), Acceptable		0,00
No pictures to display		
Ignition key, Missing, E - Replace		150,00
No pictures to display		