


VOLKSWAGEN Golf: 1HGA391

Vinnumber:	WVWZZZAUZEW367085	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	11/07/2014	Fiscalpower:	
Expertise Mileage:	85078	Power Kw:	77
Bodytype:		Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1511
Maintenance	SERVICE IN 16600KM 122D		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			30,00
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wheel cover F L, Scratch(es), E - Replace			30,00



Maintenance book, Missing, E - Replace

0,00



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display