


RENAULT Grand Scenic: 1GGX730

Vinnumber:	VF1JZ14P650246631	Versionname:	GRAND SCENIC Energy Intens 7pl.110PK
First Registrationdate:	5/02/2014	Fiscalpower:	
Expertise Mileage:	120729	Power Kw:	81
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2610
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/17/95 V LightMetal			
	Fr.L.	Continental: 1 mm	Fr.R.	Continental: 1 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	901,35
Tyre F L, Worn, E - Replace	132,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R, Scratch(es), I - Repair

100,00



Tyre F R, Worn, E - Replace

132,00



Wheel bolt cover F L, Damaged, E - Replace

13,75



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Central pillar L, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), I - Repair

100,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Central pillar R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	