



# RENAULT GRAND SCENIC: 1FGU883

|                                   |                          |              |                |
|-----------------------------------|--------------------------|--------------|----------------|
| Vinnumber:                        | <b>VF1JZ14P649292954</b> | Versionname: | <b>DCI</b>     |
| First Registrationdate:           | <b>25/06/2013</b>        | Fiscalpower: |                |
| Expertise Mileage:                | <b>137450</b>            | Power Kw:    | <b>81</b>      |
| Bodytype:                         |                          | Body color   | <b>Brown</b>   |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b> |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Steel</b>   |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>      |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>1531</b>    |
| Number of doors                   | <b>5</b>                 |              |                |
| Number of seats                   | <b>7</b>                 |              |                |
| Number head rests                 | <b>7</b>                 |              |                |
| Rims summer                       | <b>Steel</b>             |              |                |
| Category                          | <b>Passenger Car</b>     |              |                |
| Oil level                         | <b>OK</b>                |              |                |
| Registration Certificate Car (BE) | <b>No</b>                |              |                |

## Options

|                                |                              |                      |
|--------------------------------|------------------------------|----------------------|
| Radio CD                       |                              | Central consol F     |
| GPS storage                    | <b>SD</b>                    | Luggage cover        |
| GPS storage                    |                              | Rear parking sensors |
| Windows electric F             |                              |                      |
| Windows electric R             |                              |                      |
| Cruise Control                 |                              |                      |
| Steering wheel multifunctional |                              |                      |
| Radio multimedia               |                              |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |
| Type of climate control        | <b>Autom climate control</b> |                      |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

## Degree of wear

|               |                             |                          |       |                          |
|---------------|-----------------------------|--------------------------|-------|--------------------------|
|               | <b>205/60/16/96 H Steel</b> |                          |       |                          |
| Summer tyres: | Fr.L.                       | <b>Continental: 6 mm</b> | Fr.R. | <b>Continental: 6 mm</b> |
|               | Re.L.                       | <b>Michelin: 5 mm</b>    | Re.R. | <b>Michelin: 5 mm</b>    |

## Assistance equipment

|                                          |            |      |              |
|------------------------------------------|------------|------|--------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b>   |
| Total cost ex VAT                        |            |      | <b>14,40</b> |
| Bumper R, Scratch(es), Acceptable        |            |      | <b>0,00</b>  |
| <i>No pictures to display</i>            |            |      |              |
| Outer valance R, Scratch(es), Acceptable |            |      | <b>0,00</b>  |
| <i>No pictures to display</i>            |            |      |              |
| Wheel cover F R, Scratch(es), Acceptable |            |      | <b>0,00</b>  |
| <i>No pictures to display</i>            |            |      |              |

No pictures to display

|                                         |       |
|-----------------------------------------|-------|
| Bumper moulding F R, Crack, E - Replace | 14,40 |
|-----------------------------------------|-------|



|                                                    |      |
|----------------------------------------------------|------|
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
|----------------------------------------------------|------|

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                 |      |
|---------------------------------|------|
| Seat cover R, Stain, Acceptable | 0,00 |
|---------------------------------|------|

No pictures to display

|                                                         |      |
|---------------------------------------------------------|------|
| Wheel aperture R L, Dent(s) and scratch(es), Acceptable | 0,00 |
|---------------------------------------------------------|------|

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Seat cover F L, Stain, Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                         |      |
|-----------------------------------------|------|
| Wheel aperture R R, Dent(s), Acceptable | 0,00 |
|-----------------------------------------|------|

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Seat cover F R, Stain, Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display