



## VOLKSWAGEN GOLF VII: SH0624

|                                    |                   |              |                               |
|------------------------------------|-------------------|--------------|-------------------------------|
| Vinnumber:                         | WVWZZZAUZGP002378 | Versionname: | 1.6 TDI 77KW DSG 8MT HIGHLINE |
| First Registrationdate:            | 22/06/2015        | Fiscalpower: |                               |
| Expertise Mileage:                 | 54055             | Power Kw:    | 77                            |
| Bodytype:                          | Hatchback         | Body color:  | Black                         |
| Gearbox:                           | Automatic         | Paint type:  | Metallic                      |
| Transmission:                      | Front             | Rims summer: | Aluminium                     |
| Fueltype:                          | Diesel            | Oil level:   | OK                            |
| Battery functioning:               | Yes               | Parking lot: | 1423                          |
| Number of doors:                   | 5                 |              |                               |
| Number of seats:                   | 5                 |              |                               |
| Number head rests:                 | 5                 |              |                               |
| Rims summer:                       | Aluminium         |              |                               |
| Category:                          | Passenger Car     |              |                               |
| Oil level:                         | OK                |              |                               |
| Registration Certificate Car (BE): | Yes               |              |                               |

## Options

|                                |                       |
|--------------------------------|-----------------------|
| Windows electric F             | Seats electric F L    |
| Windows electric R             | Central consol F      |
| Cruise Control                 | Luggage cover         |
| Steering wheel multifunctional | Front parking sensors |
| Seats F heated                 | Rear parking sensors  |
| Radio multimedia               | Type of Tow bar       |
| Type of headlighting           | Headlighting Xenon    |
| Type of GPS                    | GPS big screen color  |
| Type of Lining                 | Lining leather        |
| Type of climate control        | Autom climate control |
| Adaptive cruise control        | No Tow bar            |

## Limited Technical Inspection

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Power steering      | Yes |
| Idle position       | OK | Sound engine        | OK  |
| Engine startingtime | OK | Clutch test         | OK  |
| Exhaust gass        | OK | Wiper fluid level   | OK  |
| Handbrake           | OK | Transmission        | OK  |
|                     |    | Lighting            | OK  |
|                     |    | Wiperblades         | OK  |

## Degree of wear

|               |                           |                   |       |                   |
|---------------|---------------------------|-------------------|-------|-------------------|
|               | 225/45/17/91 H LightMetal |                   |       |                   |
| Winter tyres: | Fr.L.                     | Bridgestone: 6 mm | Fr.R. | Bridgestone: 6 mm |
|               | Re.L.                     | Bridgestone: 6 mm | Re.R. | Bridgestone: 6 mm |

## Assistance equipment

|                                           |     |      |         |
|-------------------------------------------|-----|------|---------|
| Emergency spare wheel                     | Yes | Jack | Yes     |
| Total cost ex VAT                         |     |      | 2784,31 |
| Luggage space cover, Missing, E - Replace |     |      | 70,00   |



Tyre F R, Tear, E - Replace

132,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R polished, Scratch(es), E - Replace

235,20



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18




Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80




Certificate Of Conformity, Missing, E - Replace

150,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



|                                   |      |
|-----------------------------------|------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                  |      |
|----------------------------------|------|
| Windscreen, Repaired, Acceptable | 0,00 |
|----------------------------------|------|

No pictures to display

|                                                         |        |
|---------------------------------------------------------|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---------------------------------------------------------|--------|

