



VOLKSWAGEN GOLF VII: 1PXX178

Vinnumber:	WVWZZZAUZHP005556	Versionname:	1.6 TDI 66KW TRENDLINE
First Registrationdate:	10/10/2016	Fiscalpower:	
Expertise Mileage:	21050	Power Kw:	66
Bodytype:		Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2607
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Luggage cover	
Cruise Control	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	195/65/15/91 H Steel			
	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1082,98
Door F L, Repaired, Acceptable			0,00
No pictures to display			
Rearview mirror housing L, Scratch(es), Acceptable			0,00
No pictures to display			
Bonnet, Bad repair, Acceptable			0,00



Interior, Stain, Acceptable	0,00
-----------------------------	------

No pictures to display

Door R L, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Bumper R, Dent(s) and scratch(es), Le - Replace and paint	651,00
---	--------



Bodywork, Not original part, Remove lettering	0,00
---	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rocker panel inner F L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display