



RENAULT Clio: 1FRF536			
Vinnumber:	VF15R040H49578725	Versionname:	CLIO IV BER Expression 75PK
First Registrationdate:	1/10/2013	Fiscalpower:	
Expertise Mileage:	152351	Power Kw:	55
Bodytype:	Hatchback	Body color	Red
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1307
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	185/65/15/88 T Steel			
	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1099,58
Wheel cover R R, Scratch(es), E - Replace			24,00



Bonnet, Dent(s) and scratch(es), Acceptable	0,00
---	------

Wheel cover F L, Scratch(es), E - Replace		24,00
		
Bumper R, Scratch(es), Acceptable		0,00
No pictures to display		
Door R R, Bad repair, Acceptable		0,00
		
Wheel cover F R, Scratch(es), E - Replace		24,00
		
Rearview mirror housing R, Scratch(es), Acceptable		0,00
No pictures to display		
Bumper F, Scratch(es), LI - Repair and paint (complete)		169,44
		
Wing R L, Scratch(es), LI - Repair and paint (complete)		246,56
		
Tailgate, Scratch(es), LI - Repair and paint (complete)		241,34
		
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)		254,68
		
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)		115,56
		