



RENAULT Clio: VE7918

Vinnumber:	VF15RJL0H51525620	Versionname:	CLIO IV BER e-Expression St&St 90PK
First Registrationdate:	18/08/2014	Fiscalpower:	
Expertise Mileage:	101463	Power Kw:	66
Bodytype:	Hatchback	Body color	White
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	2629
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	Luggage cover
GPS storage	HD Type of Tow bar
Windows electric F	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	185/65/15/88 M-S Steel			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Total cost ex VAT	1478,28
Door F R, Dent(s), Acceptable	0,00

No pictures to display	
Bumper corner R R, Scratch(es), It - Spot repair	115,56



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

248,40



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace

24,00



Bumper F R, Scratch(es), It - Spot repair

115,56



Door R L, Dent(s), Acceptable

0,00

No pictures to display

Seat cover F L, Stain, Cleaning

25,00



Wing R L, Dent(s), PDR - Paintless dent repair

63,00



Bonnet, Dent(s), Acceptable

0,00

No pictures to display


Windscreen, Crack, E - Replace

413,76



Roof, Hail damage, PDR - Hail

425,00



Maintenance, Maintenance, Execute

0,00



Wheel cover R L, Broken, E - Replace

24,00



Wheel cover F L, Broken, E - Replace

24,00

