



VOLKSWAGEN Golf: 1GWX964

Vinnumber:	WVWZZZAUZEP594302	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	22/05/2014	Fiscalpower:	
Expertise Mileage:	129541	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2531
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Xenon
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			357,36
Door R L, Stone chip(s), Acceptable			0,00
No pictures to display			
Tailgate, Scratch(es), Acceptable			0,00
No pictures to display			
Door F R, Scratch(es), LI - Repair and paint (complete)			0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Mirror side blinker L, Broken, E - Replace

30,00

