



**VOLVO V60: 1HDC701**

|                                    |                          |              |                                 |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber:                         | <b>VV1FW8481E1205765</b> | Versionname: | <b>V60 BRE D2 Kinetic 115PK</b> |
| First Registrationdate:            | <b>23/06/2014</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                 | <b>74254</b>             | Power Kw:    | <b>84</b>                       |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                     |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                  |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Maintenance:                       | <b>UITVOEREN</b>         | Parking lot: | <b>2722</b>                     |
| Maintenance:                       | <b>NOT OK</b>            |              |                                 |
| Battery functioning:               | <b>Yes</b>               |              |                                 |
| Number of doors:                   | <b>5</b>                 |              |                                 |
| Number of seats:                   | <b>5</b>                 |              |                                 |
| Number head rests:                 | <b>5</b>                 |              |                                 |
| Rims summer:                       | <b>Aluminium</b>         |              |                                 |
| Category:                          | <b>Passenger Car</b>     |              |                                 |
| Oil level:                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                 |

**Options**

|                                |                              |                      |                          |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD                       |                              | Seats electric F L   |                          |
| GPS storage                    | <b>HD</b>                    | Central consol F     |                          |
| GPS storage                    |                              | Luggage cover        |                          |
| Windows electric F             |                              | Rear parking sensors |                          |
| Windows electric R             |                              | Type of Tow bar      | <b>Tow bar removable</b> |
| Cruise Control                 |                              |                      |                          |
| Steering wheel multifunctional |                              |                      |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                          |
| Type of Lining                 | <b>Lining leather</b>        |                      |                          |
| Type of climate control        | <b>Autom climate control</b> |                      |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>215/50/17/95 W LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>Bridgestone: 6 mm</b> | Fr.R. | <b>Bridgestone: 6 mm</b> |
|                                  | Re.L. | <b>Bridgestone: 5 mm</b> | Re.R. | <b>Bridgestone: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

Total cost ex VAT 819,24

Central pillar R, Dent(s), Acceptable 0,00



Door R L, Scratch(es), Acceptable

0,00



Door R R, Dent(s), Acceptable

0,00



Seat cover F L, Tear, Repair/replace (lump sum)

110,64



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Maintenance, Maintenance, Execute

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door panel F L, Scratch(es), Acceptable

0,00



Door F L, Dent(s), Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door panel R L, Scratch(es), Acceptable

0,00



Wing F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim R L, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Scratch(es), Acceptable 0,00

