



VOLVO V40: 1LPS452

Vinnumber:	VV1MV7431G2307287	Versionname:	2.0 D2-82 KINETIC
First Registrationdate:	6/11/2015	Fiscalpower:	
Expertise Mileage:	114376	Power Kw:	88
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2710
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 8 mm	Fr.R.	Semperit: 8 mm
	Re.L.	Semperit: 7 mm	Re.R.	Semperit: 7 mm

Assistance equipment

Total cost ex VAT	776,42
Seat cover F L, Stain, Acceptable	0,00



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------



Door R R, Dent(s), PDR - Paintless dent repair

82,80



Bumper F, Dent(s) and scratch(es), It - Spot repair

115,56



Door F L, Scratch(es), Acceptable

0,00



Interior, Dirty, Chemical cleaning

175,00



Rearview mirror housing L, Broken, E - Replace

38,47



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper R, Scratch(es), Acceptable

0,00





Rearview mirror basis L, Broken, E - Replace

157,30



Mirror side blinker L, Broken, E - Replace

91,73

