



RENAULT Scenic: 1JFX264

Vinnumber:	VF1JZ14K652044031	Versionname:	SCENIC Energy Life 110PK
First Registrationdate:	8/12/2014	Fiscalpower:	
Expertise Mileage:	106791	Power Kw:	81
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3605
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Type of Tow bar	Tow bar fixed
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H Steel				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1255,55
-------------------	----------------

Seat cover F R, Stain, Cleaning	25,00
---------------------------------	--------------



Door F R, Dent(s), PDR - Paintless dent repair 82,80



Roof pillar R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Outer door handle F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R R, Scratch(es), It - Spot repair 115,56



Bumper corner R R, Deformed / Strained, Smart repair 110,64



Door moulding Lower F R, Scratch(es), LI - Repair and paint (partial) 110,00




Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover R, Stain, Cleaning 75,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door moulding Lower R R, Scratch(es), LI - Repair and paint (partial) 110,00

