


**RENAULT Kangoo: 1FGT716**

Vinnumber:	<b>VF1KW2HB647978115</b>	Versionname:	<b>KANGOO 2PLC Expression FAP 109PK</b>
First Registrationdate:	<b>25/09/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>36881</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3533</b>
Number of doors:	<b>6</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Type of Tow bar
Steering wheel multifunctional	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>No GPS</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 T Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>729,70</b>
Tailgate, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wheel cover R R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bodywork, Not original part, Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Sliding door R, Bad repair, Acceptable			<b>0,00</b>



Trunk door R L, Dent(s), PDR - Paintless dent repair

63,00



Wheel cover F L, Scratch(es), E - Replace

30,00



Sliding door R, Scratch(es), LI - Repair and paint (complete)

318,35



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Rearview mirror housing R, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing R R, Scratch(es), Acceptable

0,00

*No pictures to display*