



SEAT ALHAMBRA: 1LLA618

Vinnumber:	VSSZZZ7NZGV708379	Versionname:	2.0 TDI 110KW STYLE ECOMOTIVE
First Registrationdate:	16/10/2015	Fiscalpower:	
Expertise Mileage:	102830	Power Kw:	110
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3626
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.
	Re.L.	Continental: 6 mm	Re.R.
			Continental: 6 mm

Assistance equipment

Total cost ex VAT	1616,71
Sliding door L, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	362,02



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Sliding door R, Scratch(es), LI - Repair and paint (complete) 522,85



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), LI - Repair and paint (complete) 369,84



Protection plate M, Strained , E - Replace 74,00



Luggage space cover, Deformed / Strained, E - Replace 288,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), Acceptable 0,00

No pictures to display