


NISSAN Qashqai: 1RPA671

Vinnumber:	SJNFDAJ11U1260292	Versionname:	QASHQAI 2WD Tekna Xtron.130PK Aut.
First Registrationdate:	9/12/2014	Fiscalpower:	
Expertise Mileage:	43676	Power Kw:	96
Bodytype:		Body color	White
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2711
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Seats electric F L
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	No Tow bar
Type of GPS	Headlighting Xenon
Type of Lining	GPS big screen color
Type of climate control	Lining leather
	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/19/92 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.
	Re.L.	Dunlop: 7 mm	Re.R.

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			646,99
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------




Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Rocker panel inner R R, Dent(s), Acceptable	0,00
---	------

No pictures to display

Rearview mirror housing R, Scratch(es), 67 - Polish	55,19
---	-------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

