

VOLKSWAGEN Golf: 1GHG552

Vinnumber:	WVWZZZAUZEP559661	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	7/02/2014	Fiscalpower:	
Expertise Mileage:	90781	Power Kw:	77
Bodytype:	Break	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2105
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	1470,58
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08





Windscreen, Scratch(es), E - Replace

487,20



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bodywork, Not original part, Acceptable

0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)

481,50

