



BMW 3: 1JAP443

Vinnumber:	WBA3K11060F836661	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	18/11/2014	Fiscalpower:	
Expertise Mileage:	165050	Power Kw:	100
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	OVER 2800KM	Parking lot:	3508
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1604,38
Wing F R, Dent(s), Le - Replace and paint			530,02



Sill outer R, Scratch(es), LI - Repair and paint (complete)

310,50



Bumper F R, Scratch(es), It - Spot repair

115,56



Bumper R, Deformed / Strained, LI - Repair and paint (complete)

259,80



Mirror side blinker L, Broken, E - Replace

30,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

358,50

