



**BMW 3: 1GDM434**

Vinnumber:	<b>WBA3D11000J625317</b>	Versionname:	<b>3 BER 318d 136PK</b>
First Registrationdate:	<b>8/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>180939</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3620</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	<b>No Tow bar</b>
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>0,00</b>
Bumper F, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Roof, Rust, Acceptable	<b>0,00</b>



Rearview mirror housing R, Scratch(es), Acceptable	0,00
----------------------------------------------------	------

*No pictures to display*

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door R R, Repaired, Acceptable	0,00
--------------------------------	------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

*No pictures to display*