



**VOLKSWAGEN Crafter 50 Extra-lang verhoogd: 1DJH917**

Vinnumber:	<b>WV1ZZZ2EZC6044182</b>	Versionname:	<b>CRAFTER 50 B/F 5.0T XLWB HR 163PK Specim</b>
First Registrationdate:	<b>1/06/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>136022</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot:	<b>LCV05</b>
Maintenance	<b>IN 10900 KM</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>3</b>		
Number head rests	<b>3</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Windows electric F		Central consol F	
Type of headlighting	<b>Headlighting Halogen</b>	Type of Tow bar	<b>Tow bar fixed</b>
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/75/16/105 R Steel</b>				
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	711,11
Trunk door R L, Not original part, P - Check	0,00



Dashboard, Hole, Smart repair

110,64



Bodywork, Not original part, Remove lettering 0,00



Sliding door R, Dent(s), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, Acceptable 0,00

No pictures to display

Roof, Not original part, Acceptable 0,00



Trunk door R R, Dent(s) and scratch(es), It - Spot repair 115,56



Sill outer R, Rust, Acceptable 0,00



Bumper corner R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Wheel bolt cover F R, Broken, E - Replace 15,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15

