



PEUGEOT 308: 1HHU007

Vinnumber:	VF3LBBHXHES177570	Versionname:	308 BER BlueHDi Allure STT 116PK
First Registrationdate:	28/07/2014	Fiscalpower:	
Expertise Mileage:	76997	Power Kw:	85
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 24100 KM	Parking lot:	4124
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	463,56
-------------------	---------------

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door frame R R, Dent(s), Acceptable	0,00
-------------------------------------	-------------

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Sill outer L, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56

