



MERCEDES GLA: 1HCT236

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------|
| Vinnumber: | WDC1569081J025253 | Versionname: | GLA 200 CDI 136PK |
| First Registrationdate: | 19/06/2014 | Fiscalpower: | |
| Expertise Mileage: | 191509 | Power Kw: | 100 |
| Bodytype: | Hatchback | Body color: | Red |
| Gearbox: | MAN 6 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1306 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 1 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|--|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Steering wheel multifunctional | Rear parking sensors |
| Radio multimedia | Type of Tow bar |
| Type of headlighting | Headlighting Xenon |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining artificial leather and alcantara |
| Type of climate control | Manual climate control |
| | No Tow bar |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|------------------------|-------|------------------------|
| | 235/50/18/101 V LightMetal | | | |
| Winter tyres: | Fr.L. | Firestone: 1 mm | Fr.R. | Firestone: 1 mm |
| | Re.L. | Firestone: 4 mm | Re.R. | Firestone: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

Total cost ex VAT 911,98

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18



| | |
|-------------------------------------|--------|
| Seat F L compl, Broken, E - Replace | 480,00 |
|-------------------------------------|--------|



| | |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|--------|
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|

