


OPEL Astra: 1GAU469

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | WOLPD8EWXE8024425 | Versionname: | ASTRA BRE ecoFLEX Business 110PK |
| First Registrationdate: | 10/12/2013 | Fiscalpower: | 81 |
| Expertise Mileage: | 106975 | Power Kw: | 81 |
| Bodytype: | Break | Body color: | Dark Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2206 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-------------------------------|
| Radio CD | Luggage cover |
| Windows electric F | Rear parking sensors |
| Cruise Control | Type of Tow bar |
| Steering wheel multifunctional | No Tow bar |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| Winter tyres: | 215/60/16/99 H LightMetal | | | |
| | Fr.L. | Michelin: 6 mm | Fr.R. | Michelin: 6 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |
| | | | | |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 315,08 |
|-------------------|--------|

| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|------|
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|---|--------|
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 290,08 |
|---|--------|



| | |
|---------------------------|-------|
| Interior, Stain, Cleaning | 25,00 |
|---------------------------|-------|



| | |
|--------------------------------------|------|
| Roof, Chemical polution, 67 - Polish | 0,00 |
|--------------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display