



OPEL ASTRA SPORTS TOURER: 1RGA138

Vinnumber:	W0LBD8EL1H8028867	Versionname:	1.6 CDTI 81KW ECOFLEX S/S EDITION
First Registrationdate:	14/12/2016	Fiscalpower:	
Expertise Mileage:	175306	Power Kw:	81
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1511
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H Steel			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 898,74

Wing F R, Dent(s), LI - Repair and paint (complete) 268,18



A-pillar right, Dent(s) and scratch(es), It - Spot repair

115,56



Rearview mirror basis L, Broken, E - Replace

152,20



Wheel cover F R, Scratch(es), E - Replace

30,00



Seat cover F L, Stain, Cleaning

25,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

307,80

