



VOLVO V40: 1HPX064

Vinnumber:	YV1MV8481F2194962	Versionname:	V40 D2 Base 115PK
First Registrationdate:	9/09/2014	Fiscalpower:	
Expertise Mileage:	111334	Power Kw:	84
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3115
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear


	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1109,79
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80





Rear window, Scratch(es), E - Replace 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 462,35




Wing R R, Scratch(es), Acceptable 0,00

No pictures to display
 Door F R, Dent(s) and scratch(es), It - Spot repair 115,56



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Mirror side blinker R, Broken, E - Replace 30,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display
 Wing F R, Scratch(es), Acceptable 0,00

No pictures to display
 Wing F L, Scratch(es), Acceptable 0,00

No pictures to display