



DACIA Lodgy: 1EEE150

Vinnumber:	UU1JSDBC647945722	Versionname:	LODGY Laur?ate 7pl. 107PK
First Registrationdate:	6/11/2012	Fiscalpower:	
Expertise Mileage:	85479	Power Kw:	79
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2427
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


185/65/15/88 T Steel				
Summer tyres:	Fr.L.	Semperit: 3 mm	Fr.R.	Semperit: 3 mm
	Re.L.	Semperit: 5 mm	Re.R.	Semperit: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 961,78

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 241,34



Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door F L - Dent(s), PDR - Painless dent repair 63,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44



Wheel cover F R, Scratch(es), E - Replace

24,00



Wheel cover R R, Scratch(es), E - Replace

24,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

246,56



Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace

24,00

