



CITROËN C4 Picasso: 1EGK287

Vinnumber:	VF7UA9HR8CJ737830	Versionname:	GR.C4 PICASSO Bus.GPS FAP 112PK
First Registrationdate:	26/11/2012	Fiscalpower:	
Expertise Mileage:	171383	Power Kw:	82
Bodytype:		Body color:	.
Gearbox:	MAN 6 VIT	Body color:	Black
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	1528
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1978,50
Door F R, Dent(s), LI - Repair and paint (complete)	414,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Scratch(es), Acceptable 0,00



Bonnet, Dent(s), Acceptable 0,00



Moulding windscreen R, Chemical polution, LI - Repair and paint (partial) 95,00



Moulding windscreen L, Chemical polution, LI - Repair and paint (partial) 95,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 342,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wheel bolt cover R L, Missing, E - Replace

5,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Scratch(es), Acceptable

0,00



Wheel bolt cover F L, Missing, E - Replace

5,00



Wing R R, Dent(s) and scratch(es), Acceptable

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wheel bolt cover R R, Missing, E - Replace

5,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20

