



**AUDI A4: 1GCS571**

Vinnumber:	<b>WAUZZZ8K0EA090093</b>	Versionname:	<b>A4 BER TDie 136PK</b>
First Registrationdate:	<b>2/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>146098</b>	Power Kw:	<b>100</b>
Bodytype:		Body color	<b>Dark Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3324</b>
Number of doors	<b>4</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	<b>No Tow bar</b>
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 2 mm</b>	Fr.R.	<b>Goodyear: 2 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Total cost ex VAT	1125,28
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80





Door F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Wing F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Bonnet, Stone chip(s), Acceptable 0,00

*No pictures to display*