



AUDI A3: 1GTQ065

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber: | WAUZZZ8V4E1033048 | Versionname: | A3 SED Attraction 105PK |
| First Registrationdate: | 25/04/2014 | Fiscalpower: | |
| Expertise Mileage: | 160633 | Power Kw: | 77 |
| Bodytype: | Berline | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3501 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|-------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Rear parking sensors | |
| GPS storage | SD | Type of Tow bar | No Tow bar |
| Windows electric F | | | |
| Windows electric R | | | |
| Cruise Control | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 205/55/16/91 H LightMetal | | | | |
| Winter tyres: | Fr.L. | Continental: 5 mm | Fr.R. | Continental: 5 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

Assistance equipment

| | | | |
|--|------------|------|---------------|
| Emergency spare wheel | Yes | Jack | Yes |
| Total cost ex VAT | | | 183,00 |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |



| | |
|---------------------------------|-------|
| Seat cover F L, Stain, Cleaning | 25,00 |
|---------------------------------|-------|



| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|-------|
| Bonnet, Dent(s), PDR - Paintless dent repair | 63,00 |
|--|-------|

