



BMW 4 COUPE: 1KSE034

Vinnumber:	WBA4P510X0K311834	Versionname:	2.0 418D (100KW)
First Registrationdate:	22/06/2015	Fiscalpower:	
Expertise Mileage:	146964	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4513
Battery functioning:	Yes		
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover
GPS storage		Front parking sensors
GPS storage	HD	Rear parking sensors
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining Alcantara	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

255/40/18/96 Y LightMetal				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 2604,43

Door F L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer L, Deformed / Strained, Forfeit

25,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

302,16



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

406,02



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)

369,84



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

264,21



Alloy rim F R, Scratch(es), E - Replace

277,44





Sill outer R, Scratch(es), LI - Repair and paint (complete)

372,60



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

302,16

