



BMW 4 GRAN COUPE: 1NGN853

Vinnumber:	WBA4E71000G549244	Versionname:	2.0 418D (110KW) GRAN COUPE
First Registrationdate:	19/02/2016	Fiscalpower:	
Expertise Mileage:	112662	Power Kw:	110
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2310
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/18/92 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

	Runflat	Yes
--	----------------	------------

Total cost ex VAT	58,80
-------------------	--------------

Alloy rim R L polished, Scratch(es), Acceptable	0,00
---	-------------



Alloy rim R R polished, Scratch(es), Acceptable

0,00



Windscreen, Stone chip(s), Windscreen repair

58,80



Wing R L, Repaired, Acceptable

0,00



Alloy rim F L polished, Scratch(es), Acceptable

0,00



Alloy rim F R polished, Scratch(es), Acceptable

0,00



Bumper R, Repaired, Acceptable

0,00

