



BMW 3 TOURING: TR9056

Vinnumber:	WBA8H510X0K741197	Versionname:	2.0 318D (110KW) XDRIVE TOURING
First Registrationdate:	12/04/2016	Fiscalpower:	
Expertise Mileage:	75068	Power Kw:	110
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2804
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	211,80
--------------------------	---------------

Bumper F, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper R, Dent(s), H. Repaired paint (complete)	244,80
--	---------------

