



**RENAULT Trafic: 1GJA056**

|                                    |                                 |              |  |
|------------------------------------|---------------------------------|--------------|--|
| Vinnumber:                         | <b>VF1JLB7B3EY545953</b>        | Versionname: | <b>TRAFIC PAS.Phas.III L2H1 Expr.FAP 115PK</b> |
| First Registrationdate:            | <b>20/02/2014</b>               | Fiscalpower: |  |
| Expertise Mileage:                 | <b>160533</b>                   | Power Kw:    | <b>84</b>                                      |
| Bodytype:                          | <b>Bus</b>                      | Body color:  | <b>White</b>                                   |
| Gearbox:                           | <b>MAN 6 VIT</b>                | Paint type:  | <b>Metalic</b>                                 |
| Transmission:                      |                                 | Rims summer: | <b>Steel</b>                                   |
| Fueltype:                          | <b>Diesel</b>                   | Oil level:   | <b>OK</b>                                      |
| Battery functioning:               | <b>Yes</b>                      | Parking lot: | <b>1508</b>                                    |
| Number of doors:                   | <b>5</b>                        |              |  |
| Number of seats:                   | <b>5</b>                        |              |  |
| Number head rests:                 | <b>5</b>                        |              |  |
| Rims summer:                       | <b>Steel</b>                    |              |  |
| Category:                          | <b>Light Commercial Vehicle</b> |              |  |
| Oil level:                         | <b>OK</b>                       |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>                      |              |  |

**Options**

|                                |                               |                      |                      |
|--------------------------------|-------------------------------|----------------------|----------------------|
| Radio CD                       |                               | Central consol F     |                      |
| Windows electric F             |                               | Luggage cover        |                      |
| Cruise Control                 |                               | Rear parking sensors |                      |
| Steering wheel multifunctional |                               | Type of Tow bar      | <b>Tow bar fixed</b> |
| Type of headlighting           | <b>Headlighting Halogen</b>   |                      |                      |
| Type of GPS                    | <b>No GPS</b>                 |                      |                      |
| Type of Lining                 | <b>Lining fabrics</b>         |                      |                      |
| Type of climate control        | <b>Manual climate control</b> |                      |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                              |                         |       |                         |
|---------------|------------------------------|-------------------------|-------|-------------------------|
|               | <b>215/65/16/109 R Steel</b> |                         |       |                         |
| Winter tyres: | Fr.L.                        | <b>Vredestein: 8 mm</b> | Fr.R. | <b>Vredestein: 8 mm</b> |
|               | Re.L.                        | <b>Vredestein: 9 mm</b> | Re.R. | <b>Vredestein: 9 mm</b> |

**Assistance equipment**

|   |         |
|---|---------|
| Total cost ex VAT                                       | 1108,39 |
| Wing R R, Scratch(es), LI - Repair and paint (complete) | 231,15  |




|   |        |
|---|--------|
| Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 238,76 |
|---|--------|



Roof, Dent(s), LI - Repair and paint (complete)

457,13



Bumper R, Scratch(es), LI - Repair and paint (complete)

158,85



Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Windscreen, Tear, E - Replace

0,00



Wheel cover F R, Missing, E - Replace

22,50

