



**VOLKSWAGEN Passat: 1GMB823**

Vinnnumber:	<b>VWVZZZ3CZEE128027</b>	Versionname:	<b>PASSAT VAR Comfortline BMT 105PK</b>
First Registrationdate:	<b>7/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>135690</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>.</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color:	<b>Blue</b>
Transmission:	<b>Front</b>	Paint type:	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer:	<b>Aluminium</b>
Battery functioning:	<b>Yes</b>	Oil level:	<b>OK</b>
Number of doors:	<b>5</b>	Parking lot:	<b>4726</b>
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		
Level control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/55/16/97 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Semperit: 2 mm</b>	Fr.R.	<b>Semperit: 2 mm</b>
	Re.L.	<b>Semperit: 6 mm</b>	Re.R.	<b>Semperit: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 382,67

Wing R L, Scratch(es), Acceptable 0,00



Door F L, Dent(s), Acceptable

0,00



Floor covering F L, Worn, Smart repair

64,32



Bonnet, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R, Scratch(es), Acceptable

0,00

