


SKODA Rapid: 1HJR992

Vinnumber:	TMBAJ6NH7F4009380	Versionname:	RAPID BER Ambition DSG 90PK
First Registrationdate:	4/08/2014	Fiscalpower:	
Expertise Mileage:	84493	Power Kw:	66
Bodytype:	Berline	Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3124
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/60/15/84 M-S Steel				
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2131,58
Wing R L, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Boot cover, Broken, E - Replace			50,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 307,80



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 462,35



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 290,08



Seat cover R R, Dirty, Cleaning 25,00



Maintenance, Maintenance, Execute 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 259,80



Wheel cover F R, Broken, E - Replace 30,00



Seat cover F R, Dirty, Cleaning 25,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Dirty, Cleaning 25,00



Windscreen, Tear, E - Replace 0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wheel cover R R, Broken, E - Replace 30,00



Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Remove lettering	0,00
<i>No pictures to display</i>	