



VOLVO V40: 1LHY184

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------|
| Vinnumber: | VV1MV7431G2300024 | Versionname: | 2.0 D2-82 KINETIC |
| First Registrationdate: | 2/10/2015 | Fiscalpower: | |
| Expertise Mileage: | 66735 | Power Kw: | 88 |
| Bodytype: | Break | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2207 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | HD | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|----------------------|-------|----------------------|
| 205/55/16/91 H LightMetal | | | | |
| Winter tyres: | Fr.L. | Pirelli: 4 mm | Fr.R. | Pirelli: 4 mm |
| | Re.L. | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|------|
| Total cost ex VAT | 0,00 |
|-------------------|------|

| | |
|--|------|
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|--|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|-----------------------------------|------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display