



VOLKSWAGEN TOURAN: 1NDN773

Vinnnumber:	WVGZZZ1TZGW546413	Versionname:	1.6 TDI SCR 81KW BMT TRENDLINE
First Registrationdate:	28/01/2016	Fiscalpower:	
Expertise Mileage:	187217	Power Kw:	81
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1427
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	SD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 H Steel				
Winter tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1845,64
-------------------	----------------

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
---------------------------------------------------------------------	-------------



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Rearview mirror housing R, Broken, LI - Repair and paint (complete)

115,56



Bonnet, Stone chip(s), Acceptable

0,00



Wheel cover F R, Scratch(es), E - Replace

36,00



Wheel cover R R, Scratch(es), E - Replace

36,00



Bumper R, Scratch(es), Acceptable

0,00



Door R R, Dent(s), LI - Repair and paint (complete)

382,02



Rearview mirror housing L, Scratch(es), Acceptable

0,00



Wing F R, Dent(s), Acceptable

0,00



Tailgate, Dent(s), LI - Repair and paint (complete)

362,02



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Ignition key, Missing, E - Replace

150,00

No pictures to display