



AUDI A3 SPORTBACK: 1KCB309

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | WAUZZZ8V5FA138635 | Versionname: | 1.6 TDI ULTRA ATTRACTION SPORTBACK |
| First Registrationdate: | 30/03/2015 | Fiscalpower: | |
| Expertise Mileage: | 161211 | Power Kw: | 81 |
| Bodytype: | Hatchback | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3331 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD | | Central consol F | |
| GPS storage | SD | Luggage cover | |
| GPS storage | | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | Tow bar removable |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------------|-------|--------------------------|-------|--------------------------|
| 205/55/16/94 MS LightMetal | | | | |
| Summer tyres: | Fr.L. | Bridgestone: 6 mm | Fr.R. | Bridgestone: 6 mm |
| | Re.L. | Firestone: 6 mm | Re.R. | Firestone: 6 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |



| | |
|-------------------|---------------|
| Total cost ex VAT | 830,00 |
|-------------------|---------------|

| | |
|--|-------------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|-------------|

No pictures to display

| | |
|--|-------------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|--|-------------|

No pictures to display

| | |
|---|--------|
| Door R L, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|  | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bonnet, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Ignition key, Not functioning (well), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper F, Broken, Le - Replace and paint | 735,00 |
|  | |