



BMW 3: 1GCS566

Vinnumber:	WBA3X310X0D358950	Versionname:	3 GRAN TURISMO 328iA 245PK Aut.
First Registrationdate:	2/01/2014	Fiscalpower:	
Expertise Mileage:	122988	Power Kw:	180
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	REMVLOEISTOF	Parking lot:	3708
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/18/99 V LightMetal				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		793,32
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16

