



FORD TOURNEO: 1TXR921

Vinnumber:	WF03XXTTG3EL50319	Versionname:	
First Registrationdate:	14/03/2014	Fiscalpower:	
Expertise Mileage:	509423	Power Kw:	114
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3403
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	9		
Number head rests:	9		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/105 R LightMetal				
Summer tyres:	Fr.L.	Michelin: 1 mm	Fr.R.	Michelin: 1 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1056,37
-------------------	----------------

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	---------------



Aerial, Broken, E - Replace 11,25



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Tyre F R, Worn, E - Replace 105,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 362,02



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Tyre F L, Worn, E - Replace 105,00



Bumper moulding F R, Scratch(es), E - Replace 10,80



Maintenance, Maintenance, Execute 0,00

