



RENAULT MEGANE GRANDTOUR: 1NNU776

Vinnnumber:	VF1KZ0C0H55060411	Versionname:	1.5 ENERGY DCI 95 TOMTOM? EDITION
First Registrationdate:	29/03/2016	Fiscalpower:	
Expertise Mileage:	150239	Power Kw:	70
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4115
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H Steel			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT		641,55
-------------------	--	--------

Bonnet, Stone chip(s), Acceptable		0,00
-----------------------------------	--	------

No pictures to display

Roof, Dent(s), Acceptable		0,00
---------------------------	--	------

No pictures to display

Windscreen, Stone chip(s), Acceptable		0,00
---------------------------------------	--	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), LI - Repair and paint (complete)

308,20



Aerial, Missing, E - Replace

15,00

