


RENAULT CLIO: 1KBA314

Vinnumber:	VF15RJL0H52519230	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	23/03/2015	Fiscalpower:	
Expertise Mileage:	107638	Power Kw:	66
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2625
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 T Steel			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	780,82
-------------------	---------------

Tailgate, Chemical polution, 67 - Polish	0,00
--	-------------

No pictures to display

Rear spoiler, Chemical polution, LI - Repair and paint (complete)	115,56
---	---------------



Wheel cover F R, Deformed / Strained, E - Replace

24,00



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)

385,20



Wheel cover R R, Scratch(es), Acceptable

0,00

No pictures to display

Bodywork, Not original part, Acceptable

0,00

No pictures to display

Wheel cover F L, Deformed / Strained, E - Replace

24,00



Bonnet, Dent(s), LI - Repair and paint (complete)

232,06

