



OPEL Movano 3500 MWB Med.High Roof: 1GEZ755

Vinnumber:	WOLMRFESCEB049632	Versionname:	MOVANO 3500 B/F L2H2 ecoFL.(E5)125PK
First Registrationdate:	21/01/2014	Fiscalpower:	
Expertise Mileage:	201125	Power Kw:	92
Bodytype:	Transporter	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	NOT OK
Maintenance:	NOT OK	Parking lot:	LCV30
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	NOT OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/65/16/102 R Steel			
Winter tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	31,50
-------------------	-------

Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

No pictures to display

Bodywork, Not original part, Remove lettering	0,00
---	------

No pictures to display

Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------



Bodywork, No damage, Acceptable 0,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Trunk door R R, Not original part, E - Replace 3,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Mirror side blinker R, Broken, E - Replace 28,50



Wing F R, Dent(s), Acceptable 0,00

No pictures to display

Sliding door R, Dent(s), Acceptable 0,00

No pictures to display

Steering wheel, Worn, Acceptable 0,00

