



MERCEDES Sprinter 300: 1CQM182			
Vinnumber:	WDB9066331S655749	Versionname:	SPRINTER 313 B/F 3500kg MWB A2H1 129PK
First Registrationdate:	2/02/2012	Fiscalpower:	
Expertise Mileage:	223163	Power Kw:	95
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV03
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options			
Radio CD		Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS base		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		



Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	235/65/16/113 R Steel			
Winter tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 3 mm	Re.R.	Uniroyal: 3 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	689,58
Bumper R, Dent(s) and scratch(es), E - Replace	192,00



Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02
	
Seat cover F L, Worn, Acceptable	0,00
	
Door moulding Lower R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Rust, It - Spot repair	115,56

