



**VOLKSWAGEN PASSAT VARIANT: 1UFK787**

Vinnumber:	<b>WVWZZZ3CZHE138193</b>	Versionname:	
First Registrationdate:	<b>24/04/2018</b>	Fiscalpower:	
Expertise Mileage:	<b>10</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4611</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Central consol F
GPS storage	<b>HD</b>	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/60/16/95 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 9 mm</b>	Fr.R.	<b>Continental: 9 mm</b>
	Re.L.	<b>Continental: 9 mm</b>	Re.R.	<b>Continental: 9 mm</b>

**Assistance equipment**

Total cost ex VAT	<b>115,56</b>
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	<b>115,56</b>

