



VOLKSWAGEN Golf: 1JKP216

Vinnumber:	VWZZZAUZFW167251	Versionname:	GOLF BER Highline 105PK
First Registrationdate:	12/01/2015	Fiscalpower:	
Expertise Mileage:	111548	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3827
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-Alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	409,40
-------------------	---------------

Tailgate, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Roof, Dent(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

No pictures to display

Door panel F R, Tear, Acceptable	0,00
----------------------------------	------

No pictures to display

Rocker panel inner F L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R R, Dent(s), PDR - Paintless dent repair	102,60
--	--------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Bad repair, Acceptable	0,00
----------------------------------	------

No pictures to display


Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Rocker panel inner F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Wing F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R L, Bad repair, Acceptable	0,00
----------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Bad repair, LI - Repair and paint (complete)	211,80
--	--------

