



**VOLKSWAGEN TOURAN: 1JVK307**

Vinnumber:	<b>WVGZZZ1TZEW098636</b>	Versionname:	<b>1.6 CR TDI TRENDLINE BLUEMOTION TECH</b>
First Registrationdate:	<b>5/03/2015</b>	Fiscalpower:	<b>77</b>
Expertise Mileage:	<b>116736</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>4105</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Vredestein: 5 mm</b>	Fr.R.	<b>Vredestein: 5 mm</b>
	Re.L.	<b>Vredestein: 6 mm</b>	Re.R.	<b>Vredestein: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>3083,29</b>
<b>Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)</b>			<b>369,84</b>



Wing F L, Dent(s), LI - Repair and paint (complete)

264,21



Mirror side blinker L, Broken, E - Replace

31,20



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Maintenance, Maintenance, Execute

0,00



Reflector, Broken, E - Replace

0,00



Door R R, Scratch(es), LI - Repair and paint (complete)

382,02



Interior, Dirty, Acceptable

0,00



Bumper R, Broken, Le - Replace and paint

766,80



Door R L, Dent(s), Acceptable

0,00



Parking sensor R, Missing, E - Replace

105,20



Windscreen, Stone chip(s), Acceptable

0,00



Alloy rim R R polished, Scratch(es), Acceptable

0,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Door F R, Dent(s), LI - Repair and paint (complete)

382,02



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Dent(s), Acceptable

0,00



Alloy rim F L polished, Scratch(es), Acceptable

0,00

