



VOLKSWAGEN Passat VARIANT: 1HLU446

Vinnumber:	VVWZZZ3CZEE177736	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	22/08/2014	Fiscalpower:	
Expertise Mileage:	147030	Power Kw:	77
Bodytype:		Body color:	.
Gearbox:	MAN 6 VIT	Body color:	Black
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	2528
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/97 W LightMetal				
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1591,20
Bumper R, Scratch(es), Acceptable	0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bonnet, Dent(s) and scratch(es), Acceptable

0,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Ceiling, Hole, Smart repair

64,32



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Wing R R, Scratch(es), Acceptable

0,00



Ignition key, Missing, E - Replace

150,00



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35

