



**BMW 4 Gran Coupe: KD7357**

Vinnumber:	<b>WBA4B71020D422277</b>	Versionname:	<b>4 GRAN COUPE 420dX 184PK</b>
First Registrationdate:	<b>21/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>141453</b>	Power Kw:	<b>135</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4708</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/50/17/94 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Pirelli: 7 mm</b>	Fr.R.	<b>Pirelli: 7 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT		1276,35
-------------------	--	---------

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)		308,20
---	--	--------



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), LI - Repair and paint (complete) 318,35



Bumper F, Dent(s), LI - Repair and paint (complete) 211,80



Foglight R, Crack, E - Replace 138,00

